


St.Bartholomew's Church Great Gransden

DIAGRAM OF THE SHUTTER DOORS AND LOOSE LAID HATCHES IN THE OLD BELFRY



8 Shutter doors

5 Moveable hatches

Not to scale

